

December 12, 1978

Mr. Robert Hall  
Silverleaf Garage  
3147 West Highway M  
Springfield, Missouri 65807

Dear Mr. Hall:

Please be advised that on December 9, 1978, personnel from the City of Springfield, Water Pollution Control Section, Surveillance and Enforcement Branch responded to a gasoline spill at your garage. The spillage was apparently caused by a faulty service line between your storage tanks and your dispenser, which resulted in a spill.

The ordinances of the City provide for recovery of the costs involved in abatement of a violation under emergency conditions. Payment of those costs should be made to the Director of Finance, City of Springfield, Missouri and sent to:

City Hall, Room 210  
830 Boonville  
Springfield, Missouri 65802  
Attention: Mr. Robert Schaefer, P.E.

Attached to this letter, please find a detailed explanation of the costs involved. If you have any questions, please feel free to call.

Yours truly,

Gene Pabst  
Water Pollution Control Inspector III  
Surveillance and Enforcement

GP:pg

Attachment

cc: Mr. Robert R. Schaefer, P.E., Superintendent of Sanitary Services  
Mr. Howard Wright, City Attorney  
Mr. Fred Fantazzi, Director of Finance  
Mr. John R. Nixon, Regional Administrator, Dept. of Natural Resources  
Mr. Doug Frame, Oil & Hazardous Materials Spills, E.P.A.

3147 W. HWY M

<u>Personnel Costs:</u>	<u>Burden Rate</u>	<u>Hours</u>	<u>Cost</u>
Gene Pabst	10.36	4	41.44
Robert Corson	10.88	4	43.52
			<u>\$84.96</u>

<u>Equipment Costs</u>	<u>Rate</u>	<u>Miles</u>	<u>Cost</u>
P2-7	\$.15 mile	14	2.10

<u>Material Costs</u>	<u>Rate</u>	<u>No. Used</u>	<u>Cost</u>
Oil Sorbent Sheets			
3/8" x 18" x 18"	\$52.00/100 sheets	80	\$41.60

TOTAL COST	\$128.66
------------	----------

3147 W. HWY M